CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-03-251 Date: 03/12/98 07:18

Work ID: Water Composite Sample

Date Received: 03/09/98
Date Completed: 03/11/98

Client Code: MILBANK_MFG

SAMPLE IDENTIFICATION

Sample Sample

Number Description

O1 Effluent Water Composite

Sample

Sample

Number Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only to the items tested.

This report contains a total number of pages: 02

Certified By

A Member of THE ASTBURY GROUP



Order # 98-03-251 03/12/98 07:18

TEST RESULTS BY SAMPLE

Page 2

Sample: 01AW Effluent Water Composite Collected: 03/06/98 Category: WATER

Test Description Zinc, ICAPES

Result 2.370 Limit 0.010

<u>Units</u> <u>Analyzed</u> <u>By</u> mg/L 03/11/98 JAR







ESC aboratories

Client Name:
Milbark MfG

Sampler(s) Signature:

DATE

3-6-98 7-32

Project No:

Stat.No

5933 West 71st Street * Indianapolis, IN 46278 Phone (317) 290-1471 * Fax (317) 290-1670

Project Name:

TIME COMP GRAB

X

ESG Work Order #:

STATION LOCATION ID

PIT

Kongli

CHAIN OF C

Total

Number of

Containers

N C	F (CUS	TO	DY	RE	ECO	RD			***
	d (Y or v. Code	_	/	/	/	7	7	7		Preservation Codes:
Analy	ses			//	//			//		A = Acid B = Base C = Cool 4°
<u>/_</u>	\leftarrow	\leftarrow	\leftarrow	\leftarrow	\leftarrow	\leftarrow	\leftarrow	\leftarrow	Comments	
1			├				-	-		
		-	-		_	-				
	-	-				-	-	-		
-			-	-	-	-				
			-	-		 				
				 						
Addi			nation							
	Turn	Arou	nd Tin	ne: No	orma		Rush		Report Due:	
	Are samples suspected to be: Flammable Corrosive Toxic									
	Were samples received intact and properly preserved? Yes No									
	Temp	o. Blar	ık	°C						